



DEPARTURE ROUTE DESCRIPTION

TAKE-OFF RUNWAYS 6L/R: Climb via heading 040° for vector to V23; thence via (transition) or (assigned route).

TAKE-OFF RUNWAYS 7L/R: Climb via heading 070° for vector to V23; thence via (transition) or (assigned route).

LOST COMMUNICATIONS

RUNWAYS 6L/R and 7L/R: If no transmissions are received upon reaching the LAX 7 DME, turn left heading 270°, intercept V23 to CHATY INT and resume the CHATY TWO DEPARTURE. Continue climb on course.

GORMAN TRANSITION (CHATY2.GMN): From over CHATY INT via V23 to GMN VORTAC. Cross CHATY INT at or above 5400', and CASTA INT at or above 8300'.

HENER TRANSITION (CHATY2.HENER): From over CHATY INT via V23 and FIM R-097 to FIM VORTAC. Cross CHATY INT at or above 5400'. Then proceed via FIM R-250 to HENER INT.

KWANG TRANSITION (CHATY2.KWANG): From over CHATY INT via V23 and FIM R-097 to FIM VORTAC. Cross CHATY INT at or above 5400'. Then proceed via FIM R-250 to KWANG INT.

SAN MARCUS TRANSITION (CHATY2.RZS): From over CHATY INT via V23 and FIM R-097 to FIM VORTAC. Cross CHATY INT at or above 5400'. Then proceed via FIM R-250 and RZS R-109 to RZS VORTAC.

SW-3, 26 JUN 2014 to 24 JUL 2014

SW-3, 26 JUN 2014 to 24 JUL 2014